



Manufacture Discontinue

Bulletin Number: R-2005-0298-Global
 Date: 12 September 2005

Passport 8100 Manufacture Discontinue

Manufacture Discontinue Notice Date: 01-August-2005

| | |
|------------------------------------|-------------------|
| Last Time Order Date: | 30 September 2005 |
| Last Ship Date: | 31 October 2005 |
| Manufacture Discontinue (MD) Date: | 31 October 2005 |
| Last Supported Software Release: | 3.7 |
| End of Life (EOL) Date: | 30 September 2010 |
| Market Regions Affected: | Global |

Introduction

Effective 01 August 2005, the Passport 8100 Switch family will be discontinued. The last order date is 30 September 2005. The last ship date is 31 October 2005.

Product Overview (See Table for Detail)

| Product Description | Product Engineering Code (PEC) | Replacement Product Description (If applicable) | Replacement Product Engineering Code (PEC) |
|---|--------------------------------|---|--|
| <i>Passport 8132TX Edge Switch Module</i> | <i>DS1404006</i> | <i>Ethernet Routing Switch 8300</i> | <i>DS1404077 or DS1404078</i> |
| <i>Passport 8148TX Edge Swith Module</i> | <i>DS1404007</i> | <i>Ethernet Routing Switch 8300</i> | <i>DS10404077 or DS1404078</i> |
| <i>Passport 8116FX Edge Switch Module</i> | <i>DS1404008</i> | <i>Ethernet Routing Switch 8300</i> | <i>DS1404098</i> |
| <i>Passport 8108GBIC Edge Switch Module</i> | <i>DS1404009</i> | <i>Ethernet Routing Switch 8300</i> | <i>DS1404076</i> |

| | | | |
|---|------------------|-------------------------------------|-------------------------------|
| <i>Passport 8190 Switch Management Module</i> | <i>DS1404014</i> | <i>Ethernet Routing Switch 8300</i> | <i>DS1404076</i> |
| <i>Passport 8100-2FX MDA</i> | <i>DS2033001</i> | <i>Ethernet Routing Switch 8300</i> | <i>DS1404098</i> |
| <i>Passport 8100-4FX MDA</i> | <i>DS2033002</i> | <i>Ethernet Routing Switch 8300</i> | <i>DS1404098</i> |
| <i>Passport 8100-4TX</i> | <i>DS2033003</i> | <i>Ethernet Routing Switch 8300</i> | <i>DS1404077 or DS1404078</i> |
| <i>Passport 8100 10 slot chassis bundle</i> | <i>DS1412001</i> | <i>Ethernet Routing Switch 8300</i> | <i>DS1412013</i> |
| <i>Passport 8100 6 slot chassis bundle</i> | <i>DS1412002</i> | <i>Ethernet Routing Switch 8300</i> | <i>DS142014</i> |

Software Dependencies

None.

Alternative/Replacement Products/Solutions

It is recommended that customers should move to the Ethernet Routing Switch 8300 platform.

Related Product and Sales & Marketing Bulletins (if applicable)

None.

Customer Actions

For more information, please contact your Nortel account representative. Content herein is not intended to supersede existing customer contractual commitments.

*Nortel, the Nortel logo and the Globemark are trademarks of Nortel.

Nortel is a recognized leader in delivering communications capabilities that enhance the human experience, ignite and power global commerce, and secure and protect the world's most critical information. Serving both service provider and enterprise customers, Nortel delivers innovative technology solutions encompassing end-to-end broadband, Voice over IP, multimedia services and applications, and wireless broadband designed to help people solve the world's greatest challenges. Nortel does business in more than 150 countries. For more information, visit Nortel on the Web at www.nortel.com.